



Vehicle History

Vehicle Details | **Vehicle History** | Vehicle Acquisition | Vehicle Order | Request Changes | Service Contract

Make: Mercedes-Benz Model: VITO 113CDI Current Reg: PN64 AHD Chassis: WDF63960323908486

Service/ After Sales Details

1 2 3 4 5	DocumentID	DateOfWork	Mileage	InvoiceType	DSB
	145100	26/09/2015	37716	Service	N
	145102	26/09/2015	37716	Service	N
	141914	23/02/2015	10025	Non Service	N
	961905	18/12/2014	4351	Non Service	N
	961906	18/12/2014	4351	Non Service	N

Transaction Details

Document ID: Invoice Type:

Date of Work: Mileage:

Retailer: No of Services:

PartCode	Type	Description	Labour/Parts	Payment Type
00215001		PERFORM OIL SERVICE PLUS	LABOUR	Customer
MN007603 014106		SEAL RING	PARTS	Customer
LQOILLOWASH		LOW ASH OIL/WARRANTY1	PARTS	Customer
MA651 180 01 09		OIL FILTER ELEM	PARTS	Customer

Unwarranted Mileage Details

Registration	Report Date	Test Location	Odometer Reading	InvoiceType
--------------	-------------	---------------	------------------	-------------

© Mercedes Benz UK 2018

Developed and hosted by RAPP UK (Build: -20180622-1431-2685)

[Contact Us](#) | [User Gu](#)